


NUCLEAR AND MIXED WASTE MANAGEMENT PROGRAM
HANFORD PROJECT

224-T TRUSAF

PHOTOGRAPH LOG

PHOTOGRAPHS TAKEN ON JANUARY 7, 1994 BY ALISA D. HUCKABY



NUMBER	COMMENTS:
1	Film advanced, no photo.
2	Photo of previous crack in receiving area.
3	Photo of damaged sealant (from fork lift).
4	Photo of crack in wall extending upward from floor. Photo taken near receiving area door located near southeastern corner of building.
5	Photo of sealant bubble located near door near x-ray room. Door located near southwestern end of building.
6	Photo of crack in floor near assayer control room and storage unit operations office. Crack shown in photo represents unsealed portion of pre-existing rectangular shaped crack.
7	Photo of crack in floor extending across entrance to assayer control room and storage unit operations office.
8	Photo of crack in floor of first floor hall north of assayer control room and storage unit operations office (adjacent to heating and ventilation mechanical room).
9	Photo of crack in floor of first floor hall north of assayer control room and storage unit operations office (adjacent to heating and ventilation mechanical room).
10	Photo of crack in floor of first floor hall north of assayer control room and storage unit operations office (adjacent to heating and ventilation mechanical room).
11	Photo of crack in floor of first floor hall north of assayer control room and storage unit operations office (adjacent to heating and ventilation mechanical room).
12	Photo of seam and sealed areas in floor of first floor hall (northern end of hall) north of assayer control room and storage unit operations office (adjacent to heating and ventilation mechanical room).

065-422446

**THIS PAGE INTENTIONALLY
LEFT BLANK**

13	Photo of cracks and what appears to be a sealed pipe in floor of first floor near elevator located on northwestern end of building.
14	Photo of crack in floor of first floor just outside of elevator located on northwestern end of building.
15	Photo of "penetration" holes on second floor near elevator near column labelled "D-3."
16	Photo of "penetration" holes on second floor near elevator near column labelled "D-3."
17	Photo of scratch (from fork lift) in sealant on second floor near column labelled "D-3."
18	Photo of scratch in sealant on second floor near column labelled "C-3."
19	Photo of "penetration" holes on second floor near column labelled "C-5."
20	Photo of bubbles in sealant on second floor near columns labelled "C-5" and "C-6."
21	Photo of "penetration" hole on second floor between columns labelled "D-5" and "D-6."
22	Photo of damage in sealant on second floor near column labelled "D-5."
23	Photo of damage in sealant on second floor near column labeled "C-3."
24	Photo of "penetration" hole on second floor near door labeled "208" located on the southwestern end of the building.

**THIS PAGE INTENTIONALLY
LEFT BLANK**

E Mail to Barbara Neff of the Administrative Record, H6-08.

Hi Barbara,

Would you please enter the January 7, 1994 photographs I'm sending (via mail stop system) onto the administrative record for 224-T TRUSAF. If you have any questions, please give me a call at 736-3034.

Thanx, Alisa Huckaby


9113221392

Barbara, Debbie,

This have been stamped and is being sent through the system 6/16/94. 00366008

Kim

**THIS PAGE INTENTIONALLY
LEFT BLANK**





9413224.1393

January 7, 1994 224-T TRUSAF
200 West Area Hanford Site DOE
WA 789008967
Photo taken by A.D. Huckaby
Photo # 2

JANUARY 7, 1994 224-T TRUSAF
200 West Area Hanford Site DOE
WA 789008967
Photo taken by A.D. Huckaby
Photo # 3

January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 789008967
Photo taken by A.D. Huckaby
Photo # 4

9/1/3224.1394



9443224-1395

January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE

WA 7890008967

Photo taken by A.D. Huckaby

Photo #

5

January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 7890008967

Photo taken by A.D. Huckaby



Photo # (

January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 7890008967

Photo taken by A.D. Huckaby

Photo # 7

9413224.1396



9443224.1397

January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 7890008967




Photo taken by A.D. Huckaby
Photo # 9

January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 7890008967
Photo taken by A.D. Huckaby
Photo # 9

January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 7890008967
Photo taken by A.D. Huckaby
Photo # 10

9443224-1398

9443224-599



January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 7890008967

Photo taken by A.D. Huckaby
Photo # 11

January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 7890008967

Photo taken by A.D. Huckaby


Photo # 12

January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 7890008967


Photo taken by A.D. Huckaby

Photo # 13

9443224-1400



06-1778416



January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 7890008967

Photo taken by A.D. Huckaby
Photo # 14



January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 7890008967

Photo taken by A.D. Huckaby
Photo # 15

January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 7890008967

Photo taken by A.D. Huckaby
Photo # 16

9443224-1402



94432241403

January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 7890008967

Photo taken by A.D. Huckaby

Photo #

17

January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 7890008967

Photo taken by A.D. Huckaby

Photo #

18

January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 7890008967



Photo taken by A.D. Huckaby

Photo #

19

9443224.1409

9413224-1405




January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 7890008967
Photo taken by A.D. Huckaby
Photo # 20

January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 7890008967
Photo taken by A.D. Huckaby
Photo # 21

January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 7890008967
Photo taken by A.D. Huckaby
Photo # 22

9413224.1406

94/3224.1407



January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 7890008967

Photo taken by A.D. Huckaby

Photo # 23

January 7, 1994 224-T TRUSAF
200 West Area, Hanford Site - DOE
WA 7890008967

Photo taken by A.D. Huckaby

Photo # 24

9443224-1408